

## **NONCOMPLIANCE REPORT**

Attachment to Atlanta Gold Corporation's Discharge Monitoring Reports

**February 2020** – The first week's effluent arsenic sample was in compliance and then there was a slight bump to 13 ug/L but the last week's sample went down to 11 ug/L.